03560.003365.

Cofe
PAPENT P

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Je Pat	ent of:	.)	
MICHIO HORIKOSHI ET AL.		:	: Examiner: A.C. Stevenson): Group Art Unit: 2812)
U.S. Patent No. 6,852,372 B2		:	
Issued: February 8, 2005)	
Application No.: 10/681,311)	Certificate
Filed: October 9, 2003		:	FEB 1 4 2006
For:	FABRICATION METHOD FOR ELECTRON SOURCE	:) :	of Correction
	SUBSTRATE)	February 8, 2006

ATTN: Certificate of Correction Branch Commissioner for Patents P. O. Box 1450 Alexandria, Virginia 22313-1450

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for this Certificate of Correction. Any additional fee required by this paper may be charged to Deposit Account No. 06-1205.

02/10/2006 HALI11 00000005 6852372

01 FC:1811 100.00 OP

- 2 -

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Attorney for Patentees Registration No. 42,476

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 Facsimile: (212) 218-2200 NY_MAIN 518064v1

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,852,372 B2

DATED

February 8, 2005

INVENTOR(S) :

HORIKOSHI ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 12, "a" should read --an--.

Line 25, "known;" should read --known:--.

Line 37, "Devices" J." should read --Devices", J.--.

Line 48, "this" should read -- those--.

COLUMN 4

Line 58, "proximately" should read --approximately--.

Lines 59-60, "proximately" should read --approximately--.

COLUMN 5

Line 63, ""step movement")m" should read -- "step movement")--.

COLUMN 6

Line 66, "o" should read -- or --.

No. of add'l. copies @ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,852,372 B2

DATED

February 8, 2005

INVENTOR(S) :

HORIKOSHI ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 7

Line 17, "scanning" should read --scanned--.

Line 32, "Z direction" should read -- Z directions--.

Line 61, "in to" should read --into--.

NY_MAIN 518064v1

No. of add'l. copies @ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

:

US 6,852,372 B2

DATED

February 8, 2005

INVENTOR(S) :

HORIKOSHI ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 12, "a" should read --an--.

Line 25, "known;" should read --known:--.

Line 37, "Devices" J." should read -- Devices", J.--.

Line 48, "this" should read -- those--.

COLUMN 4

Line 58, "proximately" should read --approximately--.

Lines 59-60, "proximately" should read --approximately--.

COLUMN 5

Line 63, ""step movement")m" should read -- "step movement")--.

COLUMN 6

Line 66, "o" should read -- or --.

No. of add'l. copies @ 30¢ per page



PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,852,372 B2

DATED

February 8, 2005

INVENTOR(S) :

HORIKOSHI ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 7

Line 17, "scanning" should read --scanned--.

Line 32, "Z direction" should read --Z directions--.

Line 61, "in to" should read --into--.

NY_MAIN 518064v1

No. of add'l. copies @ 30¢ per page

